$ Wes @ 4:30 Thurs

✓+ Shingles look good
✓+ hard workers

✓- 50 nails in grass
✓- Arrived 6:30 vs 7:30
✓- TAR on siding (splotchy where cleaned)
✓- scraped paint & bent 3 WATER deflectors @ front entrance & dented down spout (replace deflectors)
✓- caulking on patio beams very uneven
✓- used pine trees for restroom
✓- left 4x8 sheet OSB
✓- bent TV ANTENNA
✓- Killed grass where shingles covered for 8 hours before cleaned up