Rich Roofing Final Inspection Report

Job Number TRRR-4266
Customer Name Craig Sisco
Property Address 5950 St. Rt. 41
City/State/Zip Covington, OH. 45318

Inspected By Wes
Date 12-13-21

Chimney
- Properly Stepped ☐ Yes ☐ No
- & Counters Flashed ☐ Yes ☐ No
- Notes: N/A

Nail Placement & Depth
- Properly Stepped ☒ Yes ☐ No
- High ☐ Yes ☒ No

Wall Flashings
- Properly Installed ☒ Yes ☐ No
- Notes:

Valleys Ran Correctly ☒ Yes ☐ No

Pipe Collars
- Painted ☒ Yes ☐ No
- Nails Sealed ☒ Yes ☐ No

Heat Stacks
- Properly Shingled Around ☒ Yes ☐ No
- Painted and Sealed ☒ Yes ☐ No
- Notes:

Damper Vents
- Ice & Water Shield ☒ Yes ☐ No
- Notes:

Cap Ran Correctly ☒ Yes ☐ No

Gutter
- Nails Tight ☒ Yes ☐ No
- Cleaned Out ☒ Yes ☐ No
- Notes:

Ground Cleanup
- Notes: Good

Shingles Applied
- # of Squares: 28

Shingles Remaining on Job
- # of Bundles: 1 bdl.

Siding
- Notes: X

Interior Work
- Notes: X

Additional Notes:

Additional Work that Needs Completed: None

Corrections to be Completed:

Job Complete ☒ Yes ☐ No

Wesley Rich 12-13-21
Rich Roofing Representative — Date

12-15-21
Authorized Representative — Date

By the signature above, I represent that I am an authorized representative of the listed property and signed contract. I understand that this signature represents that all funds for the project will be released immediately to Rich Roofing and that any concerns hereafter are covered under any applicable Warranty Process.

Amanda Rachele Adams 5148 8800 0235 4360 8-25

953