Final Inspection Report

Job Number TRRR-5451

Customer Name Steve Cool

Property Address 604 Lambert Dr

City/State/Zip Piqua, OH 45356

Inspected By JCC

Date 6/3/2026

Chimney

Properly Stepped ☐ Yes ☐ No

& Counters Flashed ☐ Yes ☐ No

Notes: N/A

Nail Placement & Depth

Properly Stepped ☑ Yes ☐ No

High ☑ Yes ☐ No

Wall Flashings

Properly Installed ☑ Yes ☐ No

Notes:

Valleys Ran Correctly ☑ Yes ☐ No

Pipe Collars

Painted ☑ Yes ☐ No

Nails Sealed ☑ Yes ☐ No

Heat Stacks

Properly Shingled Around ☑ Yes ☐ No

Painted and Sealed ☑ Yes ☐ No

Notes:

Damper Vents

Ice & Water Shield ☑ Yes ☐ No

Notes:

Cap Ran Correctly ☑ Yes ☐ No

Gutter

Nails Tight ☑ Yes ☐ No

Cleaned Out ☑ Yes ☐ No

Notes:

Ground Cleanup

Notes: Good

Shingles Applied

# of Squares:

Shingles Remaining on Job

# of Bundles: 1

Siding

Notes: N/A

Interior Work

Notes: N/A

Additional Notes: Dormer Windows possible leak

Additional Work that Needs Completed:

Corrections to be Completed:

Job Complete ☑ Yes ☐ No



Rich Roofing Representative Date

Homeowner Date