Final Inspection Report

Job Number TRRR 5462
Customer Name Mary Kottmyer
Property Address 3055 Addison Carlisle Rd
City/State/Zip New Carlisle, OH 45344

Inspected By JLC
Date 6/4/2026

Chimney

Properly Stepped ☐ Yes ☐ No
& Counters Flashed ☐ Yes ☐ No
Notes: N/A

Nail Placement & Depth

Properly Stepped ☑ Yes ☐ No
High ☑ Yes ☐ No

Wall Flashings

Properly Installed ☑ Yes ☐ No
Notes:

Valleys Ran Correctly ☑ Yes ☐ No

Pipe Collars

Painted ☑ Yes ☐ No
Nails Sealed ☑ Yes ☐ No

Heat Stacks

Properly Shingled Around ☐ Yes ☐ No
Painted and Sealed ☐ Yes ☐ No
Notes: N/A

Damper Vents

Ice & Water Shield ☑ Yes ☐ No
Notes:

Cap Ran Correctly ☑ Yes ☐ No

Gutter

Nails Tight ☑ Yes ☐ No
Cleaned Out ☐ Yes ☐ No
Notes: Leaf Guard System Pre Installed

Ground Cleanup

Notes: Good

Shingles Applied

# of Squares: 28

Shingles Remaining on Job

# of Bundles: 1

Siding

Notes: N/A

Interior Work

Notes: N/A

Additional Notes: Cupola Re-Centered, Lightning Rod cable reattach. Reused existing gutter apron

Additional Work that Needs Completed:

Corrections to be Completed:

Job Complete ☑ Yes ☐ No



Rich Roofing Representative Date

Homeowner Date