Rich Roofing Final Inspection Report

Job Number TRRR-4876
Customer Name Tina Rose
Property Address 505 Spotted Doe Trail
City/State/Zip Piqua, OH 45356

Inspected By W.C
Date 05/8/2024

Chimney

Properly Stepped ☐ Yes ☐ No
& Counters Flashed ☐ Yes ☐ No
Notes: N/A

Nail Placement & Depth

Properly Stepped ☒ Yes ☐ No
High ☐ Yes ☒ No

Wall Flashings

Properly Installed ☐ Yes ☐ No
Notes: N/A

Valleys Ran Correctly ☒ Yes ☐ No

Pipe Collars

Painted ☒ Yes ☐ No
Nails Sealed ☒ Yes ☐ No

Heat Stacks

Properly Shingled Around ☒ Yes ☐ No
Painted and Sealed ☒ Yes ☐ No
Notes:

Damper Vents

Ice & Water Shield ☒ Yes ☐ No
Notes:

Cap Ran Correctly ☒ Yes ☐ No

Gutter

Nails Tight ☒ Yes ☐ No
Cleaned Out ☒ Yes ☐ No
Notes:

Ground Cleanup

Notes: Good

Shingles Applied

# of Squares: 33

Shingles Remaining on Job

# of Bundles: 0

Siding

Notes: N/A

Interior Work

Notes: X

Additional Notes:

Additional Work that Needs Completed: ~~None~~ None
No one let me know :-

Corrections to be Completed: ~~None~~ Repair awning where
boards are coming apart due to boxing on them

Job Complete ☒ Yes ☐ No

W.C 05/08/2024
Rich Roofing Representative Date

Authorized Representative Date

By the signature above, I represent that I am an authorized representative of the listed property and signed contract. I understand that this signature represents that all funds for the project will be released immediately to Rich Roofing and that any concerns hereafter are covered under any applicable Warranty Process.