Final Inspection Report

Job Number TRRR-5170
Customer Name DAN WILSON
Property Address 5 MARYMONT DRIVE
City/State/Zip PIQUA, OHIO 45356

Inspected By W.R.
Date 6-20-25

Chimney
- Properly Stepped [X] Yes [ ] No
- & Counters Flashed [X] Yes [ ] No
- Notes:

Nail Placement & Depth
- Properly Stepped [X] Yes [ ] No
- High [ ] Yes [X] No

Wall Flashings
- Properly Installed [X] Yes [ ] No
- Notes:

Valleys Ran Correctly [X] Yes [ ] No

Pipe Collars
- Painted [X] Yes [ ] No
- Nails Sealed [X] Yes [ ] No

Heat Stacks
- Properly Shingled Around [ ] Yes [ ] No
- Painted and Sealed [ ] Yes [ ] No
- Notes: N/A

Damper Vents
- Ice & Water Shield [X] Yes [ ] No
- Notes:

Cap Ran Correctly [X] Yes [ ] No

Gutter
- Nails Tight [X] Yes [ ] No
- Cleaned Out [X] Yes [ ] No
- Notes:

Ground Cleanup
- Notes: Good

Shingles Applied
- # of Squares: 41 sqr.

Shingles Remaining on Job
- # of Bundles:

Siding
- Notes: X

Interior Work
- Notes:

Additional Notes:

Additional Work that Needs Completed: X

Corrections to be Completed: 1X4 X8 on jacuzzi Covers

Job Complete [X] Yes [ ] No



Wes Rich 6-20-25
Rich Roofing Representative — Date

Richard D. Wilson
Homeowner — Date