Final Inspection Report

Job Number _____

Customer Name Kent Newbright

Property Address 2240 Loramie Washington

City/State/Zip Houston, OH 45333

Inspected By Wes

Date 5-15-26

Chimney

Properly Stepped ☒ Yes ☐ No

& Counters Flashed ☒ Yes ☐ No

Notes: _____

Nail Placement & Depth

Properly Stepped ☒ Yes ☐ No

High ☐ Yes ☒ No

Wall Flashings

Properly Installed ☐ Yes ☐ No

Notes: N/A

Valleys Ran Correctly ☒ Yes ☐ No

Pipe Collars

Painted ☒ Yes ☐ No

Nails Sealed ☒ Yes ☐ No

Heat Stacks

Properly Shingled Around ☐ Yes ☐ No

Painted and Sealed ☐ Yes ☐ No

Notes: N/A

Damper Vents

Ice & Water Shield ☐ Yes ☐ No

Notes: N/A

Cap Ran Correctly ☒ Yes ☐ No

Gutter

Nails Tight ☒ Yes ☐ No

Cleaned Out ☒ Yes ☐ No

Notes: _____

Ground Cleanup

Notes: Good

Shingles Applied

# of Squares: 14

Shingles Remaining on Job

# of Bundles: 1

Siding

Notes: X

Interior Work

Notes: X

Additional Notes: _____

Additional Work that Needs Completed: _____

Corrections to be Completed: None

Job Complete ☒ Yes ☐ No



Wes Rich 5-15-26

Rich Roofing Representative Date

Kent Newbright 5/15/26

Homeowner Date