Final Inspection Report

Job Number TRR-5361
Customer Name KAREN KOENIG
Property Address 6500 U.S. 40
City/State/Zip TIPP CITY, OHIO 45371

Inspected By Wes
Date 5-1-26

Chimney

Properly Stepped ☒ Yes ☐ No
& Counters Flashed ☒ Yes ☐ No
Notes:

Nail Placement & Depth

Properly Stepped ☒ Yes ☐ No
High ☐ Yes ☒ No

Wall Flashings

Properly Installed ☒ Yes ☐ No
Notes:

Valleys Ran Correctly ☒ Yes ☐ No

Pipe Collars

Painted ☒ Yes ☐ No
Nails Sealed ☒ Yes ☐ No

Heat Stacks

Properly Shingled Around ☐ Yes ☐ No
Painted and Sealed ☐ Yes ☐ No
Notes: N/A

Damper Vents

Ice & Water Shield ☒ Yes ☐ No
Notes:

Cap Ran Correctly ☒ Yes ☐ No

Gutter

Nails Tight ☒ Yes ☐ No
Cleaned Out ☒ Yes ☐ No
Notes:

Ground Cleanup

Notes: Good

Shingles Applied

# of Squares: 36

Shingles Remaining on Job

# of Bundles: 3

Siding

Notes: X

Interior Work


Notes: X

Additional Notes:

Additional Work that Needs Completed: None

Corrections to be Completed: None

Job Complete ☒ Yes ☐ No



Wes Rich 5-1-26
Rich Roofing Representative Date

Karen K
Homeowner Date